



Overview: Part of spill impact on 16" Tunu – Brass Creek Pipeline at Agbidiana. Picture was taken during Joint Investigation of 21<sup>st</sup> November 2015.



Close-up: Illegal fitting on 16" Tunu – Brass Creek Pipeline at Agbidiana. Picture was taken during Joint Investigation of 21<sup>st</sup> November 2015.