



Overview: Part of spill impact on Diebu Creek Flowstation 24" Flarehead Line Right of Way at Peremabiri. Picture was taken during Joint Investigation of 4th September 2015.



Close-up: Source of spill (backflow) during planned site works at Diebu Creek Flowstation 24" Flarehead Line at Peremabiri. Picture was taken during Joint Investigation of 4th September 2015.