



		E 6.837996	Date 2015/09/04
		N 4.953640	Time 14:16:53 +01:00
		Altitude 23.100 M	Speed 0.01 KPH

Overview: Part of spill impact on 20" Rumuekpe-Nkpoku Pipeline Right of Way at Omuigwor/Ibaa. Picture was taken during Joint Investigation of 4<sup>th</sup> September 2015.



		E 6.837356	Date 2015/09/04
		N 4.953253	Time 14:39:24 +01:00
		Altitude 23.000 M	Speed 1.09 KPH

Overview: Part of spill impact on 20" Rumuekpe-Nkpoku Pipeline Right of Way at Omuigwor/Ibaa. Picture was taken during Joint Investigation of 4<sup>th</sup> September 2015.



Close-up: Drilled hole on 20" Rumuekpe-Nkpoku Pipeline at Omuigwor/Ibaa. Picture was taken during Joint Investigation of 5<sup>th</sup> September 2015.