



Overview: Part of spill impact on 28" Bomu-Bonny Pipeline Right of Way at Bodo West. Picture was taken during Joint Investigation of 13th September 2015.



Close-up: Illegal fitting on 28" Bomu-Bonny Pipeline at Bodo West. Picture was taken during Joint Investigation of 13th September 2015.