



Overview: Fire on 28" Nkpoku-Bomu Pipeline Right of Way at Norkpo. Picture was taken during Joint Investigation of 5<sup>th</sup> September 2015.



Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline Right of Way at Norkpo. Picture was taken during Joint Investigation of 6<sup>th</sup> September 2015.



Close-up: Multiple drilled holes clustered together pictured after plugging on 28" Nkpoku-Bomu Pipeline at Norkpo. Picture was taken during Joint Investigation of 6<sup>th</sup> September 2015.