



Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline Right of Way at Kporghor/Gio. Picture was taken during Joint Investigation of 8th September 2015.



Close-up: Clamp illegally removed on 28" Nkpoku-Bomu Pipeline at Kporghor/Gio. Picture was taken during Joint Investigation of 8th September 2015.