



Close-up: Spill point on Etelebou Flowstation Manifold at Ogboloma. Picture was taken during Joint Investigation of 21st September 2015.