


Overview: Part of spill impact on 28" Nkpoku – Bomu Pipeline Right of Way at Kporghor. Picture was taken during Joint Investigation of 13<sup>th</sup> September 2015.



Close-up: Illegal fitting on 28" Nkpoku – Bomu Pipeline at Kporghor. Picture was taken during Joint Investigation of 13<sup>th</sup> September 2015.