


Overview: Part of spill impact on 14" Okordia – Rumuekpe Pipeline Right of Way at Ikarama. Picture was taken during Joint Investigation of 20th September 2015.



Close-up: Hacksaw cut on 14" Okordia – Rumuekpe Pipeline at Ikarama. Picture was taken during Joint Investigation of 20th September 2015.