




**Overview:** Part of spill impact on 20" Rumuekpe-Nkpoku Pipeline Right of Way at Omukpobu. Picture was taken during Joint Investigation of 16<sup>th</sup> September 2015.



**Close-up:** Hacksaw cut on 20" Rumuekpe-Nkpoku Pipeline at Omukpobu. Picture was taken during Joint Investigation of 16<sup>th</sup> September 2015.