



Overview: Part of spill impact on 24" Trans Escravos Pipeline Right of Way at Sokebolou. Picture was taken during Joint Investigation of 28<sup>th</sup> September 2015.



Close-up: Illegal fitting on 24" Trans Escravos Pipeline at Sokebolou. Picture was taken during Joint Investigation of 28<sup>th</sup> September 2015.