



Overview: Part of spill impact on 20" Kolocreek-Rumekpe Trans Niger Pipeline Right of Way at Oda. Picture was taken during Joint Investigation of 1st October 2015.



Close-up: Illegal fitting on 20" Kolocreek-Rumekpe Trans Niger Pipeline at Oda. Picture was taken during Joint Investigation of 1st October 2015.