



Overview: Spread of oil observed on Etelebou Well6T Right of Way. Picture was taken during Joint Investigation of 5th November 2015.



Close-up: No source of leak observed on Etelebou Well6T. Picture was taken during Joint Investigation of 5th November 2015.