



Overview: Part of spill impact on 12" Imo River 2-Ogale Trans Niger Pipeline at Owaza. Picture was taken during Joint Investigation of 9th August 2016.



Close-up: Illegal fitting on 12" Imo River 2-Ogale Trans Niger Pipeline at Owaza. Picture was taken during Joint Investigation of 9th August 2016.