


Overview: Part of spill impact on 6" Obigbo North-Ogale Pipeline at Ogale. Picture was taken during Joint Investigation of 26<sup>th</sup> August 2016.



Close-up: Illegal fitting on 6" Obigbo North-Ogale Pipeline at Ogale. Picture was taken during Joint Investigation of 26<sup>th</sup> August 2016.