



Overview: Part of spill impact on 28" Nkpoku - Bomu Pipeline Right of Way at Kporghor/Gbam. Picture was taken during Joint Investigation of 3rd February 2016.



Close-up: Illegal fitting on 28" Nkpoku - Bomu Pipeline at Kporghor/Gbam. Picture was taken during Joint Investigation of 3rd February 2016.