



Overview: Part of spill impact on 6" Mini Nta – Ahia Bulkline Right of Way at Akpabu. Picture was taken during Site visit of 8<sup>th</sup> February 2016.



Close-up: Damage due to 3<sup>rd</sup> party impact on 6" Mini Nta – Ahia Bulkline at Akpabu. Picture was taken during Joint Investigation of 9<sup>th</sup> February 2016.