




Overview: Part of spill impact on 6" Seibou Bulkline2 Right of Way at Azagbene. Picture was taken during Joint Investigation of 24th February 2016.



Close-up: 3mm hole on 6" Seibou Bulkline2 at Azagbene. Picture was taken during Joint Investigation of 24th February 2016.