



Overview: Part of spill impact on Belema Well1L 4" Flowline Right of Way at Belema. Picture was taken during Joint Investigation of 24<sup>th</sup> February 2016.



Close-up: Illegal fitting on Belema Well1L 4" Flowline at Belema. Picture was taken during Joint Investigation of 24<sup>th</sup> February 2016.