


Overview: Part of spill impact on 28" Bomu-Bonny Trans Niger Pipeline Right of Way at Anyaminima/Oloma. Picture was taken during Site Visit of 16th February 2016.



Close-up: Illegal fitting on 28" Bomu-Bonny Trans Niger Pipeline at Anyaminima/Oloma. Picture was taken during Joint Investigation of 5th March 2016.