





Overview: Part of spill impact on KoloCreek Well3T Flowline Right of Way at Otusega. Picture was taken during Joint Investigation of 19th January 2016.



Close-up: Hacksaw cut on KoloCreek Well3T Flowline at Otusega. Picture was taken during Joint Investigation of 19th January 2016.



Close-up: Hacksaw cut on KoloCreek Well3T Flowline at Otusega. Picture was taken during Joint Investigation of 19th January 2016.



Close-up: Hacksaw cut on KoloCreek Well3T Flowline at Otusega. Picture was taken during Joint Investigation of 19th January 2016.