



Overview: Part of spill impact on 28" Bomu-Bonny Pipeline Right of Way at Bodo City. Picture was taken during Joint Investigation of 11th February 2016.



Close-up: Illegal fitting on 28" Bomu-Bonny Pipeline at Bodo City. Picture was taken during Joint Investigation of 12th February 2016.