


Overview: Part of spill impact 18" Assa-Rumuekpe Pipeline at Elele-Alimini Ihuaba. Picture was taken during Joint Investigation of 12th July 2016.



Close-up: Drilled Hole on 18" Assa-Rumuekpe Pipeline at Elele-Alimini Ihuaba. Picture was taken during Joint Investigation of 14th July 2016.