



Overview: Part of spill impact on 16" Zarama - Gbaran CPF Bulkline at Okotiana. Picture was taken during Joint Investigation of 13<sup>th</sup> July 2016.



Close-up: Illegal fitting on 16" Zarama-Gbaran CPF Bulkline at Okotiana. Picture was taken during Joint Investigation of 15<sup>th</sup> July 2016.