



Overview: Part of spill impact on 16" Tunu-Brass Creek Pipeline Riser at Peretorugbene. Picture was taken during Joint Investigation of 19th July 2016.



Close-up: Inward Dent/Tear on 16" Tunu-Brass Creek Pipeline Riser at Peretorugbene. Picture was taken during Joint Investigation of 19th July 2016.