




Overview: Part of spill impact on 28" Bomu-Bonny Pipeline at Okolo Launch. Picture was taken during Joint Investigation of 11th June 2016.



Close-up: Illegal fitting on 28" Bomu-Bonny Pipeline at Okolo Launch. Picture was taken during Joint Investigation of 24th June 2016.