



Overview: Part of spill impact on 8" Afam Well 27 T Flowline at Ayama. Picture was taken during Joint Investigation of 28th June 2016.



Close-up: Illegal fitting on 8" Afam Well 27 T Flowline at Ayama. Picture was taken during Joint Investigation of 28th June 2016.