



Overview: Part of spill impact on 20" Kolocreek-Rumuekpe Pipeline Riser at Aminigboko. Picture was taken during Joint Investigation of 19th October 2016.



Close-up: Inward dent, explosive tear on 20" Kolocreek-Rumuekpe Pipeline Riser at Aminigboko. Picture was taken during Joint Investigation of 19th October 2016.