



Overview: Part of spill impact on 48" Forcados Export Pipeline Right of Way at Ogulagha. Picture was taken during overfly on 9th June 2016.



Close-up: Spill point on 48" Forcados Export Pipeline at Ogulagha. Picture was taken during Pipeline Repair works on 13th July 2016.