


Overview: Part of spill impact on Etelebou Flow Station Right of Way at Ogboloma. Picture was taken during Joint Investigation of 17th March 2016.



Close-up: Source of leak on Etelebou Flow Station at Ogboloma. Picture was taken during Joint Investigation of 17th March 2016.