



Overview: Oil sheen observed on Soku Well 21L Wellhead Right of Way at Soku. Picture was taken during Joint Investigation of 8th March 2016.



Close-up: Oil stains observed on Soku Well 21L Wellhead at Soku. Picture was taken during Joint Investigation of 8th March 2016.