



Overview: Part of Spill Impact on 12" Imo River – Ogale Pipeline Right of Way at Owaza. Picture was taken during Joint Investigation of 17th May 2016



Close-up: Illegal fittings on 12" Imo River – Ogale Pipeline at Owaza. Picture was taken during Repair Operation on 18th May 2016.