



Overview: Part of Spill Impact on Obigbo Well28 Right of Way at Imeh. Picture was taken during Joint Investigation of 18th May 2016.



Close-up: Leak on Obigbo Well28 at Imeh. Picture was taken during Joint Investigation of 18th May 2016.