



Overview: Part of spill impact on 20" Otumara-Escravos Pipeline at Ogidigben. Picture was taken during Joint Investigation of 31st October 2016.



Close-up: Tampered Clamp on 20" Otumara-Escravos Pipeline at Ogidigben. Picture was taken during Joint Investigation of 31st October 2016.