

JOINT INVESTIGATION REPORT

INCIDENT NO: 1760110 JIV report S/N: Nº 0000224

(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)

A. GENERAL INFORMATION:

1. Spill incident Number: 1760110 2. Type of incident* OIL SPILL
3. Name of Location ETELEBOU WELL IIT WELLHEAD
4. Name of nearest community AKENFA 5. State: BAYELSA 6. LGA YENAGDA
7. Type of Production facility/Installation WELLHEAD
8. Asset owner/District THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LTD (SPDC) / LAND

B. INCIDENT INFORMATION:

9. Details of incident
a. Date of incident: 30TH NOVEMBER 2016
b. Start date/time of investigation: 2ND DECEMBER 2016
c. Investigation End date: 2ND DECEMBER 2016 Actual investigation duration, days: ONE (1) DAY
d. Description of spill point environment

- Firm soil Loose soil Recently excavated area
 Under water Swampy Exposed pipe surface
 Well Platform (on Water LAND) Drill Rig

Additional observations around the spill point:

NOT APPLICABLE

e. Description of leak point (tick as applicable):

- | | | |
|---|---|--|
| <input type="checkbox"/> Drilled hole | <input type="checkbox"/> Hack saw cut | <input type="checkbox"/> Tear (_____). |
| <input type="checkbox"/> Complete Rupture | <input type="checkbox"/> Inward dent. | <input checked="" type="checkbox"/> Well head tampering |
| <input type="checkbox"/> Failed Weld-on illegal hot tap valve | <input type="checkbox"/> Failed Clamp, | <input type="checkbox"/> Missing Pipeline/Flowline |
| <input type="checkbox"/> Crude oil theft (illegal bunkering) point. | <input type="checkbox"/> Saver-pit over flow | <input type="checkbox"/> Third party tampering with Clamp |
| <input type="checkbox"/> Third party tampering with valve setting | <input type="checkbox"/> Bulging Outward | <input type="checkbox"/> Third party tampering with flange, |
| <input type="checkbox"/> Flare System/Bund wall failure | <input type="checkbox"/> Cold vent | <input type="checkbox"/> Surge vessel overflow, |
| <input type="checkbox"/> Valve Failure | <input type="checkbox"/> Relief valve failure | <input type="checkbox"/> Accidental 3 rd party equipment impact |
| <input type="checkbox"/> Others(specify) _____ | | |

f. Incident caused by:

- Third party interference (Sabotage ; crude theft ; Line theft ; Accidental 3rd party damage
 Operational Others (including Mystery spills) _____

*This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire.

JOINT INVESTIGATION REPORT

INCIDENT NO: 176 0110 JIV report S/N: No 0000224

g. Spill point coordinates

WGS 84

h. Measuring unit

Northing: Latitude	Easting: Longitude
5.00494	6.36825
 	
 	

C. RISK ASSESSMENT

10. Type of environment:

- Land Swamp Water Seasonal swamp Shoreline/Waterfront

i. Type of environment to which oil has spread:

- Land Swamp Water River (identify) _____

ii. Weather condition

- Rain Sunny Dry Wet Windy Hot Cool

11. Distance from the nearest sensitive habitat

- Government reserved and designated protected area
- Drinking water source
- Built up area
- Farmlands
- Fish Farm/Pond
- Fishing net
- Others (specify).

[.m] } NONE SEEN
[.m] } WITHIN VICINITY
[.m]
[.m]
[.m]
[.m]

12. Containment measures put in place:

- Booms Trench Dyke Natural depression Pit None

Others: _____

13. Any pictures or video coverage?

[N]

14. Further response/repair initiated as at the time of JIV?

[N]

If yes to item 14, give brief description:

WELL SHUT-IN AND SECURED

15. Was there any disruption to the investigation?

[Y]

JOINT INVESTIGATION REPORT

INCIDENT NO: 1760110 JIV report S/N: N^o 0000224

G. INCIDENT INFORMATION:

a. Impacted Area Details

- Total calculated area of impact 0.11 Ha.
- Impact within R.O.W YES
- Impact outside R.O.W No

b. Volume of oil recovered before completion of JIV (V_{rec}):

Recovered oil V_{rec} :	<u>NIL</u>	Barrels
---------------------------	------------	---------

Controlled recovery/evacuation from source with no impact to environment:

<u>NIL</u>	Barrels
------------	---------

c. Net Estimated Spilled Volume $V_{Est}(bbls)^* =$

76.76 BBLs

Estimated Reported Volume** $V_{rep}(bbls) =$

77 BARRELS

*Notes:

- Volume estimation was done using an excel based tool. (see attached for details on the calculation)
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for estimating the spilled in the box below:

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m^3 to barrels is Volume (m^3) x 6.29; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 13.3 bbl ----- Reported volume = 16 bbl
Calculated volume = 0.35 bbl ----- Reported volume = 0.4 bbl
Calculated volume = 0.01 bbl ----- Reported volume = 0.1 bbl

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviation) of the JIV procedure to use appropriate steps for volume estimation; record the calculation in a plain sheet of paper and attach to the JIV report

JOINT INVESTIGATION REPORT

INCIDENT NO: 1760110 JIV report S/N: N^o 0000224

d. General Status of the site

- | |
|--|
| i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out <input type="checkbox"/> |
| ii. Investigation of the incident site showed that there is residual impact on site requiring further works <input checked="" type="checkbox"/> |

e. Representatives

<p>This report was filled, agreed and signed by the following joint investigation team representatives:</p> <ul style="list-style-type: none">• Host Community: <input checked="" type="checkbox"/>• Department of Petroleum Resources (DPR): <input checked="" type="checkbox"/>• National Oil Spill Detection and Response Agency (NOSDRA): <input checked="" type="checkbox"/>• State Ministry of Environment (SME): <input checked="" type="checkbox"/>• Asset Owner: <input checked="" type="checkbox"/>• Signatories agree with reported findings: <input checked="" type="checkbox"/>• Separate DPR form has been filled out with same findings: <input checked="" type="checkbox"/> <p style="text-align: right;"><i>Tick as applicable</i></p>

JOINT INVESTIGATION REPORT

INCIDENT NO: 1760110 JIV report S/N:

Nº 0000224

f. Appendix 1: Overview sketch of the site

