



Overview: Part of spill impact on Benisede Well 6S Wellhead at Ojobo. Picture was taken during Joint Investigation of 8<sup>th</sup> December 2016.



Close-up: Position of stolen surface safety valve (AVA) on Benisede Well 6S Wellhead at Ojobo. Picture was taken during Joint Investigation of 8<sup>th</sup> December 2016.