



Overview: Part of spill impact 18" Assa-Rumuekpe Pipeline at Egbeda. Picture was taken during Joint Investigation of 2nd November 2016.



Close-up: Illegal fitting on 18" Assa-Rumuekpe Pipeline at Egbeda. Picture was taken during Joint Investigation of 25th November 2016.