




Overview: Part of spill impact 28" Bomu-Bonny Pipeline at Okolo Launch. Picture was taken during Joint Investigation of 22<sup>nd</sup> October 2016.



Close-up: Tampered clamp on 28" Bomu-Bonny Pipeline at Okolo Launch. Picture was taken during Joint Investigation of 23<sup>rd</sup> October 2016.