



Overview: Part of Spill Impact on 12" Imo River – Ogale Pipeline Right of Way at Ogale. Picture was taken during Joint Investigation of 21st September 2016.



Close-up: Illegal fitting on 12" Imo River – Ogale Pipeline at Ogale. Picture was taken during Joint Investigation of 21st September 2016.