



Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline at Gio. Picture was taken during Preliminary site visit of 28th September 2016.



Close-up: Inward dent on 28" Nkpoku-Bomu Pipeline at Gio. Picture was taken during Joint Investigation of 30th September 2016.