




Overview: Part of spill impact on 8" Nkali-Imo River 2 Pipeline (Breathing Tube Box) at Umuedu-Okwara. Picture was taken during Joint Investigation of 10th September 2016.



Close-up: Tampered Kerotest Valve on 8" Nkali-Imo River 2 Pipeline (Breathing Tube Box) at Umuedu-Okwara. Picture was taken during Joint Investigation of 10th September 2016.