



Overview: Part of Spill Impact on Otamiri Well5 Flowline Right of Way at Abara. Picture was taken during Joint Investigation of 21<sup>st</sup> September 2016.



Close-up: Leak point on Otamiri Well5 Flowline at Abara. Picture was taken during Joint Investigation of 21<sup>st</sup> September 2016.