



Overview: Part of spill impact on 20" Rumuekpe-Nkpoku Trans Niger Pipeline at Ibaa. Picture was taken during Joint Investigation of 11th November 2016.



Close-up: Drilled hole on 20" Rumuekpe-Nkpoku Trans Niger Pipeline at Ibaa. Picture was taken during Joint Investigation of 11th November 2016.