



Overview: Part of spill impact on 20" Otumara-Escravos pipeline Right of Way at Ugboegungun. Picture was taken during Joint Investigation of 25th August 2017.



Close-up: Illegal fitting on 20" Otumara-Escravos pipelines at Ugboegungun. Picture was taken during Joint Investigation of 25th August 2017.