



Overview: Part of spill impact on Forcados KTI Emulsion Heater Treatment Unit at Ogulagha. Picture was taken during Joint Investigation of 10th JAugust 2017.



Close-up: Back flow from Continuous Oil Containment Drain Pit on Forcados KTI Emulsion Heater Treatment Unit at Ogulagha. Picture was taken during Joint Investigation of 10th JAugust 2017.