




**Overview:** Part of spill impact on 28" Nkpoku-Bomu Pipeline Right of Way at Rumukwurushi. Picture was taken during Joint Investigation of 2<sup>nd</sup> September 2017.



**Close-up:** Illegal fittings on 28" Nkpoku-Bomu Pipeline at Rumukwurushi. Picture was taken during Joint Investigation of 2<sup>nd</sup> September 2017.