




Overview: Part of spill impact on 20" Kolo Creek - Rumuekpe Pipeline at Odau. Picture was taken during Joint Investigation of 3<sup>rd</sup> September 2017.



Close-up: Illegal fitting on 20" Kolo Creek - Rumuekpe Pipeline at Odau. Picture was taken during Joint Investigation of 3<sup>rd</sup> September 2017.