



Close-up: Location of observed seepage (Storm Water Drain) at Soku Gas Plant Condensate Spiking pump area at Elem-Sangama. Picture was taken during Joint Investigation of 27th March 2018.