



Overview: Part of spill impact on 20"Rumuekpe-Nkpoku Pipeline Right of Way at Ibaa. Picture was taken during Joint Investigation of 29<sup>th</sup> December 2017.



Close-up: Drilled Hole on 20"Rumuekpe-Nkpoku Pipeline at Ibaa. Picture was taken during Joint Investigation of 31<sup>st</sup> December 2017.