




Overview: Part of spill impact on 28" Bomu-Bonny Pipeline Right of Way at Patrick Waterside. Picture was taken during Joint Investigation of 19<sup>th</sup> December 2017.



Close-up: Illegal fitting on 28" Bomu-Bonny Pipeline at Patrick Waterside. Picture was taken during Joint Investigation of 19<sup>th</sup> December 2017.